
5th NIES INTERNATIONAL FORUM


Assessment of Groundwater Quality in Western Area along Yangon River Jue Jue, Cho Cho Thin Kyi, Win Win Zin

Water Resources Engineering, Civil Engineering Department, Yangon Technological University

Introduction

Groundwater is a renewable and invisible resource and it is needed to be sustainably managed and it plays an important role in the social and economic growth of a country. In the absence of fresh water resources, groundwater is exploited to meet the demand exerted by various sectors. As in other urban areas of the world, the development of economic activities and the growth of population in Yangon city have led to the increased exploitation of natural resources including water. In Yangon where almost 10% of the total population of the country is living, YCDC's served population is about 39% in the year of 2015/2016 field surveys. Since the water supplied by YCDC is about 39% and the left 61% have to rely on groundwater, lakes and rivers. Most of the residents rely on their private tube wells and therefore the number of authorized or unauthorized tube wells tapping into groundwater is increasing. This would lead excessive use of groundwater which can result groundwater quality degradation through salt water/ sea water intrusion due to depletion of groundwater table. It is therefore necessary to have a detailed knowledge on the groundwater resource of Yangon city.





16°46'0"N-

16°45'0"N

Study Are

Current Water Sources that supply


Yangon	
Gyobyu Reservoir	27 MGD
Phugyi Reservoir	54 MGD
Hlawga Reservoir	14 MGD
Ngamoeyeik WTP (1st phase)	45 MGD
Ngamoeyeik WTP (2nd phase)	45 MGD
YCDC Tube Wells (425 nos.)	16 MGD
Total Water Supply Capacity	201 MGD

Main Water Source Surface water (92%) Groundwater (8%)

Private tube wells with no statistics

ရန်ကုန်နည်းပညာတက္ကသိုလ်

ON TECHNOLOGICAL







Parameters	WHO Guidelines	IS-10500:2012 Guidelines	Unit
pH	6.5-8.5	6.5 to 8.5	-
TDS	1000	500-2000	(mg/l)
EC	1500	700-3000	(µS/cm)
Turbidity	5	1-5	(NTU)
Iron	0.3	0.3	(mg/l)
Chloride	250	250-1000	(mg/l)
Total Hardness	500	200-600	(mg/l)
Total Alkalinity	250	200-600	(mg/l)

- the river.
- Based on the historical data and current sample data shows an increase in EC along the buffer lines.
- The most significant line is Buffer 400, which is near the tidal river, Yangon River.
- Based on the EC, Cl and Salinity results, it can be seen that depletion of groundwater table occurs in the study area.

Recommendations

- Groundwater Extraction should be controlled in the areas where vulnerability to sea water intrusion occurs.
- More water quality parameters should be tested for domestic uses as this research tested 9 parameters for salt water intrusion especially.